

From: Joseph Vitale
To: [Geiger, William](#)
Subject: Metal Bank
Date: Friday, June 24, 2016 9:31:20 AM
Attachments: [image001.png](#)

Hi Will:

We need some issues clarified for the removal of the crushed stone.

- The plan says "CEI will pick up the stone" with no mention of expected % removal, or acceptable amount that can remain on-site. Bruce's email mentioned removing "the vast majority of stone", but it is still unclear what amount that means, or how it will be determined that they have satisfied the requirement. I suggest less than 10% remain.
- Is there a limit to how deep into the cap CEI should go in an effort to remove stone, considering no material will be imported to backfill the area? I suggest less than 6 inches.
- CEI would like confirmation that the crushed stone and associated fines/dirt as a result of this removal effort can all be placed on the berm. This is consistent with the approval vegetation restoration plan.

If possible, I would like a response this morning. Thanks for your help.

Regards,

Joseph P Vitale, PE, LSP

MS Civil Eng., MBA
Principal Consultant
Office 617 946 6115
Mobile 617 721 2766
jvitale@ramboll.com

Ramboll Environ
20 Custom House Street, Suite 800
Boston, MA 02110
www.ramboll-environ.com



My email address has changed to jvitale@ramboll.com. Please make a note of this in your contact records. I will continue to receive email at the jvitale@environcorp.com address.

This message contains information that may be confidential, privileged or otherwise protected by law from disclosure. It is intended for the exclusive use of the Addressee(s). Unless you are the addressee or authorized agent of the addressee, you may not review, copy, distribute or disclose to anyone the message or any information contained within. If you have received this message in error, please contact the sender by electronic reply to email@ramboll.com and immediately delete all copies of the message.